	Туре	L#	Hits	Search Text	DBs	Time Stamp	Comment s	Error Definition	Errors
1	BRS	L1	339	"solder bump" same (rotat\$3 or spin\$4)		2006/08/08 18:35			
2	BRS	L2	106		US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2006/08/08 18:36			
3	BRS	L3	23	SRIVASTAVA-KAMALESH-K.in.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2006/08/08 18:39			
4	BRS	L4	2	CULLINAN-SCHOLL-MARY-C.in.		2006/08/08 18:39			
5	BRS	L5	20	GRIFFITH-JONATHAN-H.in.		2006/08/08 18:40	,		
6	BRS	L6	16	KNARR-RANDOLPH-F.in.		2006/08/08 18:40			